

INSTALLATION NOTES

- Install continuous seal in roadway, parapet, curb, and sidewalk.
- Install anchor blocks as indicated.

Threaded Anchor __Studs with Washers

Anchor bolts shall be placed to match existing holes in neoprene joint.

SKEW LIMITATIONS

The details of the anchor blocks and the elastomeric membrane in the parapet, as shown, are for up to 50° skews. For skews greater than 50°, the anchor blocks and the elastomeric membrane, installed according to dimension "D", might require modifications to insure a minimum clearance of 1/2" from centerline of anchor studs to edge of parapet opening. The anchor blocks and the elastomeric membrane shall also be installed to the top of the parapet with the anchor studs spaced at ±12" cts.

Std. Anchor Bolts

Cast in place


AJB

VHV

Steffen


AJB VHV

AT CURB



FORMING BLOCKOUT **SKETCH**

STATE OF ILLINOIS DEPARTMENT OF TRANSPORTATION



CROSS SECTION



Contract Number:

GENERAL NOTES


Continuous Seal Neoprene Expansion Joint shall consist of molded anchor blocks of elastomer and steel, field assembled over continuous lenaths of elastomeric membrane.

The elastomeric membrane shall be premolded with a single or a double upward convolution that will have a "memory" to return to its molded position upon joint closure.


The convolution length shall be such that the extended length will not be greater than the manufactured length when the joint is fully expanded in its design range and will not protrude above the anchor blocks when the joint is fully compressed.

Joint openings shall be adjusted according to Article 503.10(c) of the Standard Specifications when the deck is poured at an ambient temperature other than 50° F.


The parapet and roadway membrane shall be made continuous by an approved vulcanizing process. Lapping will not be permitted.









AT PARAPET




AT SIDEWALK OR MEDIAN




AT SIDEWALK OR MEDIAN TYPICAL END TREATMENTS



AT WALL



AT WALL



- Countersunk hole for top nut —

RECOMMENDED BLOCKOUT DETAIL

REPAIR DETAILS FAP 330 (E.B. 79th St.) COOK COUNTY SN 016-0518

c:\projects\kms\0160518.dgn 1/28/2008 2:59:19 PM

DESIGNED

CHECKED

CHECKED

DRAWN